

Manhole Inspection Summary

Manhole # S13YY_032MH

Printed On: 5/29/2009

Page 1 of 3

Inspection ☒ **Is Incomplete** Rating:

Record Plat: **13YY** Node: **032** Status: **Found**

Insp Date: **5/18/09 8:39 AM**

Incomplete Comments

Cannot Access - Car Parked On - Three Attempt

Crew: **ADS3**
Inspector: **ADS2**
Firm: **ADS**

Location Address:

Cross Street:

Manhole Type:

Location:

Ground Conditions:

☐ Prev. Rehab

Weather: **Dry**

Subject To Ponding: **None**

Comments **CNA CAR PARKED ON TOP**

Cover

Shape:

Diameter:

(in.)

Length:

(in.)

Dist A/B Grade:

(in.)

Type: **Sanitary**

Condition:

Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

Frame

Offset:

(in.)

Condition:

☐ Sound

☐ Cracked

☐ Leaks

Chimney / Frame Adjustment

☐ Exists

Material:

☐ Parged

Height:

(in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Corbel

Material:

☐ Parged

Type:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Barrel

Material:

☐ Parged

Shape:

Diameter:

(in.)

Length:

(in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Bench

☐ Exists

Material:

☐ Parged

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Channel

Material:

☐ Parged

Channel Exposure: **Fully Open**

Junc Dist: **0**

nearest .5 ft.

Azimuth:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Steps

Count:

Missing:

☐ Corroded

Surcharge

☐ Evidence Of Surcharge

Depth:

(ft.)

☐ Active Surcharge Present

